

- Models
- Production
 - Material
 - Equipment
 - Personnel
 - Events
 - Workflow**
 - Global Displays
 - Hw/Sw

- Entry Points
- Workflows
 - Workflow Schedules
 - Subprocesses
 - Faults
 - Forms

- Workflow
- Build Bike**
 - Update Production Status

Workflow Management

Configure and manage workflows, tasks, and subprocesses

- Common
- Global Viewer
 - Solution Home
 - Task Client**
- Workflow Management
- Task Management
 - Running Workflows
- Workflow Configuration
- Workflow Editor

Tasks

Sort by: Priority, Expiry Time No Filters Specified


1 Alarm Notification	Expires in 5:00 min	5:00 min
Responsibility: Operator, Canning Line 1		
1 Production Run		10:00 min
Responsibility: Operator, Canning Line 1 QA, Canning Line 1		
Step 1		11:05:00 AM
Responsibility: Operator, Canning Line 1		
Step 2		11:07:00 AM
Responsibility: Operator, Canning Line 1		
Step 3		2:00 min
Responsibility: Operator, Canning Line 1		
Step 4		Not Started
Responsibility: Operator, Canning Line 1		
Step 5		Not Started
Responsibility: QA, Canning Line 1		
2 Daily Maintenance Checks		35:00 min
Responsibility: Operator, Canning Line 1		
3 Another Task	Expires in 35:00 min	2:25 hours
Responsibility: Operator, Canning Line 1		
3 Yet Another Task	Expires in 45:00 min	45:00 min
Responsibility: Operator, Canning Line 1		

Work Instructions

Task Step Task

Production Run - Step 3

1. Check the belt tension adjustment bolt for looseness
2. Perform the hourly checks indicated below



Data Entry

- Check label adhesive levels
- Check label materials, should be at least 50% full
- Enter Label Pot Temperature
- Check oil levels in Conveyor 1-4 gear cases

Submit Cancel

Documents: [Canning Line SOPs](#) [ACME Canner Maintenance Manual](#)